



# Checklist for recommencing ringing

Guidance for steeplekeepers and tower captains

Don't assume nothing has happened up the tower since you last rang. After a period without ringing, there are a number of things that should be checked. Not all of these will apply to your tower. This third in a set of six guidance notes gives some key things to check before recommencing ringing.

In doing these checks, follow the guidance set out by your church for social distancing and adopt normal safe practices for accessing the ringing room and bell chamber.

## Ringling Room

Remember that the bells might have been left up

## Clock room and any intermediate spaces

Clock may have stopped and links disconnected  
(risk of tangling with bell installation)

Check pulleys still running freely

Check nothing has come dislodged and could interfere with the ropes when moving

## Bell chamber

Check nothing is obstructing any of the bells

Bells left up may have filled with water

Check for nesting birds, squirrels, etc

If work has been done in the tower check that nothing has been left in the way of bells

Inspect ropes for rot or rodent damage

Are shutters / louvres in place correctly?

Check generally that nothing untoward seems to have occurred

---

### It's not up to us

It is up to the Incumbent whether we ring or not. Re-starting ringing should be with their permission.

---

A full risk assessment covering actions needed following an extended period during which church bells have not been rung has been produced by the Central Council's Stewardship & Management workgroup and is available

- |   |   |   |                                     |
|---|---|---|-------------------------------------|
| 1 | What are we worried about?                | 4 | Running safe ringing sessions       |
| 2 | Making your tower as safe as possible     | 5 | Can I go ringing safely?            |
| 3 | <b>Checklist for recommencing ringing</b> | 6 | How bell ringers are assessing risk |



# Checklist for recommencing ringing

Guidance for steeplekeepers and tower captains

## Case Study: re-start of ringing in the Isle of Man

Ringing resumed in the Isle of Man in June following the elimination of the virus from the island. The experience at the two towers is a model for how to approach the re-start and what may have occurred.

Following lockdown in March, the DAC put together a check list of inspection during lockdown. It was only to be done by nominated persons. Those persons were expected to check all rooms within the building. Specialists (bell ringers, organists, etc) were allowed to assist, observing social distancing, lone working rules, etc. (Note that church access permissions differed on the Isle of Man)

As churchwarden at Douglas, ringer Ernie de Legh-Runciman checked the tower once a week. On the 7th April, the damage to the plaster ceiling was found. Approximately 4 m<sup>2</sup> of plasterboard in the corner of the ringing chamber had fallen down. If the tower had not been inspected, this damage would not have been found until ringing resumed, which would have delayed the re-start as a contractor was needed to complete the works.

At another tower, some louvre netting had come down over the bells which had to be removed before ringing started.

Prior to ringing, a small working party at Douglas went to the tower to check the bell installations (ropes, stay bolts, clappers, etc) before ringing the next week.



*Birds nest found after a prolonged period of no ringing*

These experiences emphasise the importance of working with the church authorities. Regular inspections are ideal, however a full inspection of the installation prior to ringing should be carried out by an experienced person.

- 1 What are we worried about?
- 2 Making your tower as safe as possible
- 3 **Checklist for recommencing ringing**
- 4 Running safe ringing sessions
- 5 Can I go ringing safely?
- 6 How bell ringers are assessing risk